



	□ 3∼ E	1 0 2		0°	250	230	280x200	-
				45° ←	190	180	180x180	
mm	kW	m/min	mm	60° ८	120	110	110x110	kg
2950x27x0,9	1,5/1,8	36/72	285					370













SHARK 281 CCS (Cut Control System) manual bandsawing machine to cut from 0° up to 60° left. Other than the manual cut mode, the sawing machine can make single cuts without operator, using the head weight control- led by a hydraulic brake: after the cut the band stops. The frame at this point is manually lifted to the position needed in order to reposition the bar to cut. In the version with pneumatic vice (MA) the vice is opened/closed by a manually-controlled valve (optional with pedal control).

A FEW FEATURES: See SHARK 281.



SHARK 281CCS



SHARK 281/281CCS



SHARK 281/281CCS



